



Slight Breaks, Major Headaches: Wind Energy Converter Failure Analysis Vignettes

Rachel Wittman, John Hasier | Intertek Engineering Consulting | Asset Integrity Management

Tower Section Fasteners - Structural




Problem — Corrosion observed on structural fasteners <1 year post installation.

Cause — Chloride salt ingress prior to installation lead to accelerated corrosion within flange.

Solution — Improve hardware tracking and remove salt residues prior to installation.

Platform Bracket – Ancillary Structural




Problem — Broken tower platform lugs prior to service life.

Cause — High-cycle fatigue during overseas transport from harmonic amplification of vibration in 3rd tower section.

Solution — Add rubber blocks/vibration dampeners during shipping.

Fiberglass Blade Support Section – Drivetrain




Problem — Cracked blade root support pin after 20,000 hours service life.

Cause — Grease ingress from bearing over-lubrication lead to delamination cracking, initiated within allowable microvoids in fiberglass.

Solution — Examine grease records and inspect blade adapter root region in high grease consumption units.

Ladder Rung – Ancillary Safety



Problem — Frequent early-life ladder rung failure at rung to siderail weld.

Cause — Welding process defects and insufficient quality control resulted in lack of fusion. Resulting reduced cross section fractured prematurely.

Solution — Operator to screen with magnetic particle testing, manufacturer to revise welding and quality control processes.

More Information



Download this poster here



Rachel.Wittman@intertek.com | John.Hasier@intertek.com | AIMEngineering.events@intertek.com

www.intertek.com/wind-wave-tidal/asset-management-wind-energy-services

www.intertek.com/aim/engineering

+1 408 745 7000